

- BULLETIN: AK211
- DATE: November 28, 2018

ATTENTION: AKEBONO CUSTOMERS AND SALES PERSONNEL

Akebono New Part Number Announcement

The Following **ProACT** Part Numbers are now available:

ACT1759, ACT1847, ACT1857, ACT1879, ACT1912

The Following **EURO** Part Numbers are now available:

EUR1663, EUR1663A, EUR1892

See Page 2 for Buyer's Guide and OE Interchange information.

For detailed application listings please visit: www.showmetheparts/akebono/

Contact information:

Edward Gerhardt (248) 489-7418 - Catalog & Data Services Manager
Kirby Pruitt (270) 234-5541 - Product Development Manager
Customer Service (phone) (866) 253-2666
Customer Service (fax) (866) 375-7451

- AKEBONO BRAKE CORPORATION // www.akebonobrakes.com
- 310 Ring Road, Elizabethtown, Kentucky 42701

Akebono Ultra-Premium Ceramic Disc Brake Pads

Bulletin: AK211
Date: November 28, 2018

- Buyers Guide

Part Number	FMSI Friction #	UPC	POP Code	Applications:	List Price	Jobber Price	Notes:	F/R	O.E. Ceramic
- Akebono - ProACT									
ACT1759	8987-D1759	821726005120	BI	Mazda; 18-14 3, 18-14 3 Sport (Mexico Production)	\$126.35	\$69.50	Premium Stainless Hardware Included	F	Yes
ACT1847	9075-D1847	821726005113	BIT	Hyundai; 17-16 Tucson, Kia: 17 Sportage	\$127.25	\$70.00	Premium Stainless Hardware Included	F	Yes
ACT1857	9085-D1857 9085-D1915	821726006196	A	Buick: 18-17 LaCrosse, Chevrolet: 17 Bolt EV, 18-16 Cruze, 18 Equinox, 18-16 Malibu, 18-16 Volt, GMC: 18 Terrain	\$117.25	\$64.50	Premium Stainless Hardware Included	R	Yes
ACT1879	9107-D1879 9039-D1805	821726006189	BIT	Lexus: 17-15 NX200t, 18 NX300, 18-15 NX300h, 17-16 RX350, 17-16 RX450h	\$118.20	\$65.00	Premium Stainless Hardware Included	R	Yes - Akebono OE
ACT1912	9143-D1912	821726005144	AI	Hyundai: 19-17 Elantra, 19-17 Ioniq, Kia: 19-17 Niro	\$127.25	\$70.00	Premium Stainless Hardware Included	F	Yes
- Akebono - EURO									
EUR1663	8891-D1663	821726107831	CI	Audi; 17-14 Q5	\$163.65	\$90.00	Includes Electronic Wear Sensor	F	Yes
EUR1663A	8891-D1663	821726107848	DI	Audi; 13 Q5, 17-16 Q5	\$163.65	\$90.00	Includes Electronic Wear Sensor	F	Yes
EUR1892	9120-D1892	821726107824	DI	BMW; 17-16 X1, Mini; 18-16 Cooper Clubman, 17 Cooper Countryman	\$156.35	\$86.00	Includes Electronic Wear Sensor	F	Yes

- OE Interchange

Part Number	Part Number	Brand
ACT1759	BJY7-33-28ZA	Mazda
ACT1847	58101-D3A00	Hyundai/Kia
	58101-D7A10	
	58101-D9A00	
ACT1857	13595651	GM
	39021615	
ACT1879	04466-0E060	Toyota
	04466-48160	
	04466-78010	
	04466-78020	
ACT1912	58101-F2A00	Hyundai/Kia
	58101-F3A00	
	58101-G2A00	
EUR1663	8R0-698-151-J	Audi/VW
	8R0-698-151-L	
	8R0-698-151-D	
	8R0-698-151-H	
	8R0-698-151-K	
EUR1663A	8R0-698-151-J	Audi/VW
	8R0-698-151-L	
	8R0-698-151-D	
	8R0-698-151-H	
	8R0-698-151-K	
EUR1892	34106882418	BMW