

- BULLETIN: AK234
- DATE: September 12, 2022

ATTENTION: AKEBONO CUSTOMERS AND SALES PERSONNEL

Akebono New Part Number Announcement

The Following ProACT Part Numbers are now available:

ACT1852, ACT1896, ACT2169, ACT2172

Contact information:

Kirby Pruitt (270) 765-3745 x-2114 - Product Development Manager
Customer Service (phone) (866) 253-2666
Customer Service (fax) (866) 375-7451

- AKEBONO BRAKE CORPORATION // www.akebonobrakes.com
- 300 Ring Road, Elizabethtown, Kentucky 42701

Akebono Ultra-Premium Ceramic Disc Brake Pads

Bulletin: AK234
Date: September 12, 2022

- Buyers Guide

Part Number	FMSI Friction #	UPC	POP Code	Applications:	List Price	Jobber Price	Distributor Price	Notes:	F/R	O.E. Ceramic
- Akebono - ProACT										
ACT1852	9081-D1852	821726006349	CI	Scion; iA 16, Toyota; Yaris 20-19, Yaris iA 18-17	\$ 124.55	\$68.50	\$41.10	Premium Stainless Hardware Included	F	Yes
ACT1896	9124-D1896	821726006400	AT	Buick; Enclave 19-18, Cadillac; XT5 20-17, Chevrolet Blazer 20-19, Traverse 19-18, GMC Acadia 20-17	\$ 153.65	\$84.50	\$50.70	Premium Stainless Hardware Included	F	Akebono Ceramic
ACT2169	9414-D2169	821726006387	AT	Ram; 1500 22-19	\$ 147.75	\$81.25	\$48.75	Premium Stainless Hardware Included	R	Yes
ACT2172	9417-D2172	821726006394	BT	Jeep; Wrangler 21-18	\$ 159.10	\$87.50	\$52.50	Premium Stainless Hardware Included	R	Yes

- OE Interchange

Part Number	Part Number	Brand
ACT1852	04465-WB001	Toyota
ACT1896	84323140	GM
	22972580	
ACT2169	68412364AC	Chrysler
	68412364AA	
ACT2172	68382538AB	Chrysler
	68382538AA	